Flood Control Project Maintenance Levee Inspections

Fall 2008 Levee Maintenance Deficiency Summary Report Overall LMA & Unit Ratings, including Boat Survey Erosion

Sacramento River Basin

NA0020 West Interceptor Canal	Overall LMA Rating	Total LMA Miles				
·	M	1.75				
					Encroad	chments
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	PO Miles	CO Miles
Trim / Thin Trees	0.24		0.24	13.71%		
Encroachments	0.04		0.04	2.29%		
Erosion / Bank Caving	0.04		0.04	2.29%		
LMA Totals:	0.32	0.00	0.32	18.29%	0.00	0.00

Flood Control Project Maintenance Levee Inspections

LMA District Cover Sheet

Fall 2008 Levee Inspection Results

West Interceptor Canal

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)						
* Overall LMA Rating (Fall Only)			M							
** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.										
* SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.										
<u>FALL INSPECTIONS:</u> The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.										
Comments										

Flood Control Project Maintenance Levee Inspections

Unit Cover Sheet

Fall 2008 Levee Inspection Results

West Interceptor Canal

	Waterwa	ıy		Bank	Unit Miles				
	Unit No. 01 Sou	th Levee		Right	1.75				
	Spring (March - May)	Summer (June - August)	Fall (September - November)		Vinter er - February)				
Date of Inspection	4/10/2008	, ,	10/14/2008		, , , , , , , , , , , , , , , , , , ,				
DWR Inspector	Bob Duffey		Bob Duffey						
Accompanied By									
Unit Maintenance Rating (Fall Only)			M						
Check one:									
 During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report. During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions. (In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition). 									
Comments One of the boxes above is to be chinformation must also be submitted DWR with any additional sheets by your records. Please mail all of this	d. This Unit Cover Sheet y September 30 (Summe s information to : DW 331	should be signed and da	ated by the LMA Represe 1 (Winter Inspection). Ple ction Reports om LL-30	entative an	d returned to				

X

Signature of LMA Representative

Date

Page 1 of 1

Flood Control Project Maintenance Levee Inspections

Levee Inspection Report By Mile - Fall 2008

West Interceptor Canal

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 South Levee	Right	1.75	10/14/2008	Bob Duffey

LMR	Levee Mile		Catamami	Loca		Rating	A ski su IC susus su k	GPS Latitude/Longitude		
Line	Start	End	- Category Item		Rating ** -ocation **		Action/Comment	Start End	ue	
1	0.23	0.25	Earthen Levee	Encroachments	LS	М	Landscaping	39.171418 ° 39.171408 ° -121.755963 ° -121.755578 °	2	
2	0.23	0.25	Earthen Levee	Encroachments	LS	М	Prunings	39.171422 ° 39.171407 ° -121.755963 ° -121.755578 °	1	
3	0.61	0.85	Earthen Levee	Trim / Thin Trees	LS	М	Trim trees to at least five feet above ground level.	39.171323 ° 39.171257 ° -121.748738 ° -121.744578 °	6	
4	0.62	0.65	Earthen Levee	Erosion / Bank Caving	LS	М	Schedule repair of erosion site prior to the next inspection.	39.171292 ° 39.171232 ° -121.748868 ° -121.748175 °	4	
5	1.67	1.67	Earthen Levee	Erosion / Bank Caving	LS	М	Note and monitor erosion site.	39.171133 ° 39.171133 ° -121.729265 °	5	

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected